


Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 1

Existing tree Existing hedgerow Grassland Existing boundaries and buildings










Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 2








Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 3








Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 4








Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 5








Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 6








Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 7








Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 8








Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 9







Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 10








Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 11








Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 12








Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 13








Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 14







Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 15







Kirkby Stephen Landscape and Visual Impact Appraisal Appendix Page 16

